

Outstanding Performance

Expect better than guaranteed!

In the short time that Sanovo Solutions has existed, substantial results have already been achieved. Several projects and assessments have been carried out with great success. Sanovo Solutions is very pleased to have achieved results better than guaranteed to the customers. Our customers can trust that their expectations are not only met, but also exceeded.

This is the case in these selected projects:

Energy assessment project

Sanovo Solutions has carried out an Energy Assessment at an egg product factory. The customer has followed the recommendations in the assessment report and the results are now showing. Compared to the energy consumption last year, the customer has saved even more than expected.

Wastewater treatment project

Sanovo Solutions has designed, supplied and supervised the installation and start-up of a wastewater treatment plant at an egg product factory. The guaranteed value was a COD of the treated effluent below 200 mg/l and the plant is fully living up to this guarantee. Even COD values as low as 25-50 mg/l are normally achieved. The customer is now saving money on wastewater disposal fees and is even considering supplying water for irrigation.

Raw water treatment project

Sanovo Solutions has designed a raw water treatment plant for removal of arsenic in the raw water for an egg product factory. The guaranteed value was a concentration of arsenic below 10 µg/l. The plant is shortly after start-up performing very well with concentrations of arsenic as low as 3-6 µg/l. Moreover, the consumption of chemicals is less than half of the expected volume.

Funding for development project

A client wanted to carry out a development project in co-operation with Sanovo Solutions. Sanovo Solutions prepared an application for grant aid and completed the regulatory processing. Based on this work, the client was granted maximum funds in the million DKK range, which makes it possible to implement the project.



Inspection of boiler for Energy Assessment



On the left: Effluent water from the WWTP



Arsenic removal plant